



HERITAGE-WTI, INC.
1250 St. George Street
East Liverpool, Ohio 43920-3400
Phone: 330-385-7337
Fax: 330-385-7813
Web Site: www.heritage-wti.com

OHSAS 18001: 2007
ISO 14001: 2004
ISO 9001: 2008

April 23, 2012
VIA UPS

Mr. George Czerniak, Chief
U.S. EPA Region V
Air Enforcement and Compliance Assurance
Branch
Mail Code AE-17J
77 West Jackson
Chicago, IL 60604

Mr. Erik Bewley
OEPA-DAPC-NEDO
Environmental Specialist
2110 E. Aurora Road
Twinsburg, OH 44087

RE: HERITAGE-WTI, INC.
EXCESSIVE EXCEEDANCE REPORTING

Dear Mr. Czerniak:

Please find enclosed a written report entitled MACT Excessive Exceedance Report for Heritage-WTI, Inc. This report is required by 40 CFR 63.1206 (c)(3)(vi) whenever there is more than ten emission standard or operating parameter exceedances that occur within a sixty-day period.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are certain penalties for submitting false information including the possibility of fine and imprisonment for knowing violations.

Thank you and if you have any questions or comments, please call me at the above number.

Sincerely,

A handwritten signature in black ink, appearing to read 'John Peterka', written over a horizontal line.

John Peterka
President
Heritage-WTI, Inc.

cc: Ed Fasco, Ohio EPA-DAPC-NEDO



Recycled Paper

MACT EXCESSIVE EXCEEDANCE REPORT

Heritage-WTI, Inc

April 23, 2012

Events

MACT Reporting Query									
#	Name	Start Time	End Time	Cause (report)	Cause Description	Corrective Actions	(hr)	(min)	(sec)
1	RJ Blowdown Flow	3/25/2012 12:05:29 PM	3/25/2012 12:07:28 PM	Operator Error - Poor Operation	Operator failed to respond to low ring jet blowdown flow.	Re-established OPL. Restarted unit.	0	1	59
2	THC	3/25/2012 1:22:29 PM	3/25/2012 2:06:28 PM	Operator Error - Combustion Air	Operator failed to provide enough combustion air to incinerator.	Increased air flow. Restarted unit.	0	43	59
3	THC	4/2/2012 5:05:24 PM	4/2/2012 5:08:22 PM	Operator Error - Line Purge	Operator initiated line purge from direct drum causing combustion upset.	Restarted unit.	0	2	58
4	THC	4/17/2012 4:42:29 PM	4/17/2012 5:42:27 PM	Operator Error - Feed Mix	Improper feed mix resulted in poor combustion and THC.	Reduced waste feeds. Restarted unit.	0	59	58
5	THC	4/18/2012 12:46:27 AM	4/18/2012 1:46:28 AM	Operator Error - Feed Prep	Improper feed prep led to poor combustion and THC.	Removed waste from mix. Restarted unit.	1	0	1
6	THC	4/18/2012 2:31:27 AM	4/18/2012 3:36:26 AM	Operator Error - Feed Prep	Improper feed prep led to poor combustion and THC.	Removed waste from mix. Restarted unit.	1	4	59
7	THC	4/18/2012 7:39:28 AM	4/18/2012 8:40:27 AM	Operator Error - Feed Prep	Improper feed prep led to poor combustion and THC.	Removed waste from mix. Restarted unit.	1	0	59
8	THC	4/18/2012 9:02:29 AM	4/18/2012 9:59:28 AM	Operator Error - Feed Prep	Improper feed prep led to poor combustion and THC.	Removed waste from mix. Restarted unit.	0	56	59
9	RJ DP	4/18/2012 9:41:27 AM	4/18/2012 11:19:11 AM	Operator Error - Poor Operation	Operator failed to respond to low ring jet blow down flow.	Regained OPL. Restarted unit.	1	37	44
10	THC	4/18/2012 4:41:30 PM	4/18/2012 5:40:30 PM	Operator Error - Feed Prep	Improper feed prep led to poor combustion and THC.	Removed waste from mix. Restarted unit.	0	59	0

** End of report **

bcc: Env. Dept
Frank Murray
Bob Buchheit
Kevin Lloyd

file name: environ/MACT/HWC MACT/exceedances/eer12_0423